


Bolt Circle Diameter (BCD)



5- Bolt Chaining

Multiplying dimension by 1.701 and you will get the correct BCD measure.

Example: $64.7 \times 1.701 = 110 \text{ mm}$

4 - Bolt Chaining

Multiplying dimension by 1.414 and you will get the correct BCD measure.

Example: $48.1 \times 1.414 = 68 \text{ mm}$

Distance (x)	BCD
--------------	-----

5 hole chainrings

34.1mm	58mm
--------	------

43.5mm	74mm
--------	------

50.6mm	86mm
--------	------

55.3mm	94mm
--------	------

64.7mm	110mm
--------	-------

71.7mm	122mm
--------	-------

76.4mm	130mm
--------	-------

79.4mm	135mm
--------	-------

84.7mm	144mm
--------	-------

4 hole chainrings

41.0mm	58mm
--------	------

45.3mm	64mm
--------	------

48.1mm	68mm
--------	------

73.6mm	104mm
--------	-------

79.2mm	112mm
--------	-------